

Mounting Instruction, right angled cable connector

Stripping Lengths		Measure a ¹⁾	Measure b
Screw contacts			
without internal cable retention		35 ⁺¹	7 ^{+1 2)}
Solder contacts			
without internal cable retention		32 ⁺¹	4 ⁺¹
Crimp contacts	0,14 – 0,5 mm ²		3 ^{+0,5}
	0,50 – 1,5 mm ²		3,5 ⁺¹
without internal cable retention		32 ⁺¹	

1) PE + 2mm 2) end splice recommended

